


# **Vehicle History Report**

## **VEHICLE DETAILS**

Chassis number <sup>1</sup> :	TE52-009587	Title information <sup>2</sup> :	<b>1</b>	Deregistered to Export	0
Manufacture date:	2011-01		<b>u</b> _		_
Make:	NISSAN	Accident / Repair:	<b>I</b> ⇒	No problem	
Model:	ELGRAND	Odometer rollback:		No problem	$\bigcirc$
Body:	DBA-TE52	Manufacturer	~		
Grade:	250 HIGHWAY STAR	recall:	9	No problem	~
Engine:	QR25DE	Safety grade <sup>3</sup> :	8	*****	0
Drive:	2WD	Contamination	۵.۵	No. of the second s	
Transmission:	AT	risk:	<b>Å</b>	No problem	

#### This vehicle does not qualify for Buyback Guarantee

#### **Average Market Price**





About Buyback Guarantee

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2024-12-11 03:30:32. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

# ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

# **ODOMETER READINGS HISTORY**

Date reported	Data source	Odometer reading (Km)
2022-02-08	MLIT	96300
2024-02-06	MLIT	111400
2024-11-21	NAA Nagoya	114739
2024-11-23	USS HAA Kobe	114739

# USE HISTORY

Use in the contaminated regions <sup>4</sup>	Radioactive contamination test fail <sup>5</sup>	Commercial use
Not reported	Not reported	Not reported

# **DETAILED HISTORY**

Event date	Location	Odometer reading (Km)	Data source	Details
2011-01			NISSAN	Manufactured
2011-02			MLIT	First registration
2022-02-08		96300	MLIT	Inspection
2024-02-06	Shizuoka	111400	MLIT	Inspection

2024-10-30	Shizuoka		MLIT	Last registration
2024-11-21	Aichi	114739	NAA Nagoya	Auctioned
2024-11-23		114739	USS HAA Kobe	Auctioned

## MANUFACTURER RECALL HISTORY


Date reported	Data source	Affected part	Details
Not reported			

## VEHICLE ASSESSMENT •

#### **Overall Collision Safety Ratings**

	Driver's	seat		Front passer	nger's seat
Points	Evaluation	Goal average	Points	Evaluation	Goal average
35.37	*****	98%	23.33	*****	97%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).



## **VEHICLE SPECIFICATION**

1st gear ratio	2.349 ~ 0.394( MANUAL MODE ATTACHING)	2nd gear ratio	-
3rd gear ratio	-	4th gear ratio	-
5th gear ratio	-	6th gear ratio	-

Additional notes	-	Airbag position, capacity	-
Body rear overhang	1020	Body type	STATION WAGON
Chassis number embossing position	FRONT FLOOR PANEL RIGHT SIDE	Classification code	0012
Cylinders	4	Displacement	2480
Electric engine type	-	Electric engine maximum output	-
Electric engine maximum torque	-	Electric engine power	-
Engine maximum power	125/5600( NET)	Engine maximum torque	245/3900( NET)
Engine model	QR25	Frame type	SOLID STRUCTURE
Front shaft weight	1040	Front shock absorber type	
Front stabilizer type	TORSION BAR TYPE	Front tires size	225/55R18 98V
Front tread	1.600	Fuel consumption	11.6
Fuel tank equipment	73	Grade	250 HIGHWAY STAR
Height	1.815	Length	4.915
Main brakes type	HYDRAULIC TYPE, FRONT: DISK BACK: DISK	Make	NISSAN
Maximum speed	180	Minimum ground clearance	0.150
Minimum turning radius	5.7	Model	ELGRAND
Model code	DBA-TE52	Mufflers number	
Rear shaft weight	900	Rear shock absorber type	
Rear stabilizer type	TORSION BAR TYPE -	Rear tires size	225/55R18 98V
Rear tread	1.600	Reverse ratio	1.750
Riding capacity	7	Side brakes type	
Specification code	16576	Stopping distance	50(100)

Transmission type	AT	Weight	1940
Wheel alignment	2WD	Wheelbase	3.000
Width	1.850		

# AUCTION DATA


### Date: 2024-11-21, Auction: NAA Nagoya, Lot #: 4163


Date:	2024-11-21	Lot #:	4163
Auction name:	NAA Nagoya	Region:	Aichi
Make:	NISSAN	Model:	ELGRAND
Reg. year:	2011	Mileage (km):	114739
Displacement (cc):	2500	Transmission:	IAT
Color:	BLACK	Model code:	TE52
Result:	sold	Auction grade:	3.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

### Date: 2024-11-23, Auction: USS HAA Kobe, Lot #: 53425

Date:	2024-11-23	Lot #:	53425
Auction name:	USS HAA Kobe	Region:	
Make:	NISSAN	Model:	ELGRAND
Reg. year:	2011	Mileage (km):	114739
Displacement (cc):	2500	Transmission:	IA
Color:	BLACK	Model code:	TE52
Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

## PHOTOS AND AUCTION SHEETS










	早些(自家用い	明白記入	2500		C DBA-TE52		Mila
53425	H23/2 18	<sup>車 名</sup> 目記 エルグラ		50 25	-ド 0ハイウェイス ター	<b>11111</b> 21110	4 /***
1.検	#	月 E	シフト	IAT			
目行	114, 739	kn	* 5	AAC	セールスポイント		
1元8 1 2 1 2 1	ėN	カラーね GAE	-		純正メーカー   アラウンドビ		
ガソリ	2			E TEN	後席フリッフ		
**  -	输入医分	ハンドル			ハーフレザー 両側オートス		F7
19121 1	6, 190 P	7 .	÷,	1 # Wa			
				草台胞	009587		
キセノンヘッドライト、インテリキー シリア							

~**		ч.	10	100
08	1	۰.	ь.	1-1

ダッシュ板ワレ シートフチシワ ホイールキズ 下層り一部サビ 外装ツヤなし 小キズ小凹うすキズ



x

×

a 高さ

(m)

08

【褐色内寸】約

<sup>1</sup> Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

#### <sup>2</sup> Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan , the vehicle is determined to be exported

<sup>3</sup> Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

<sup>4</sup> **Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

<sup>5</sup> Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT - Ministry of Land, Infrastructure, Transport and Tourism.

<sup>6</sup> Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test , rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

<sup>7</sup> **Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2024 Car VX Limited. All rights reserved.